


# ELBOW 90°



DIMENSIONAL DRAWING



PRODUCT

## DIMENSIONS

All dimensions in mm

| NO. | SIZE        | SDR         | d   | A   | L   |
|-----|-------------|-------------|-----|-----|-----|
| 1   | <b>L50</b>  | SDR11       | 50  | 55  | 113 |
| 2   | <b>L63</b>  | SDR11/SDR17 | 63  | 63  | 133 |
| 3   | <b>L75</b>  | SDR11/SDR17 | 75  | 70  | 152 |
| 4   | <b>L90</b>  | SDR11/SDR17 | 90  | 79  | 177 |
| 5   | <b>L110</b> | SDR11/SDR17 | 110 | 82  | 198 |
| 6   | <b>L125</b> | SDR11       | 125 | 79  | 215 |
| 7   | <b>L140</b> | SDR11       | 140 | 79  | 228 |
| 8   | <b>L160</b> | SDR11/SDR17 | 160 | 95  | 265 |
| 9   | <b>L180</b> | SDR11       | 180 | 80  | 267 |
| 10  | <b>L200</b> | SDR11/SDR17 | 200 | 102 | 312 |
| 11  | <b>L225</b> | SDR11/SDR17 | 225 | 105 | 337 |
| 12  | <b>L250</b> | SDR11/SDR17 | 250 | 130 | 400 |

| NO. | SIZE         | SDR         | d    | A   | L    |
|-----|--------------|-------------|------|-----|------|
| 13  | <b>L280</b>  | SDR11       | 280  | 105 | 395  |
| 14  | <b>L315</b>  | SDR11/SDR17 | 315  | 150 | 490  |
| 15  | <b>L355</b>  | SDR11/SDR17 | 355  | 107 | 468  |
| 16  | <b>L400</b>  | SDR11/SDR17 | 400  | 110 | 517  |
| 17  | <b>L450</b>  | SDR11/SDR17 | 450  | 110 | 570  |
| 18  | <b>L500</b>  | SDR11/SDR17 | 500  | 100 | 600  |
| 19  | <b>L560</b>  | SDR11/SDR17 | 560  | 100 | 666  |
| 20  | <b>L630</b>  | SDR11/SDR17 | 630  | 130 | 768  |
| 21  | <b>L710</b>  | SDR11/SDR17 | 710  | 160 | 910  |
| 22  | <b>L800</b>  | SDR11/SDR17 | 800  | 160 | 1010 |
| 23  | <b>L900</b>  | SDR11/SDR17 | 900  | 165 | 1140 |
| 24  | <b>L1000</b> | SDR11/SDR17 | 1000 | 160 | 1235 |

d = outside diameter • all other symbols as shown on the dimensional drawing